

InteliMains 1010 BTB SC

Bus Tie Breaker Controller

SW version 1.1.0

1 General information	2
2 Changes in the version 1.1.0	3
3 Changes in the version 1.0.1	4
4 Notes	5

1 General information

1.1 Version information

Version with support of IV5.2.

1.2 Clarification of Notation

Note: *This type of paragraph calls the reader's attention to a notice or related theme.*

IMPORTANT: This type of paragraph highlights a procedure, adjustment etc., which can cause a damage or improper function of the equipment if not performed correctly and may not be clear at first sight.

WARNING: This type of paragraph highlights a procedure, adjustment etc., which can cause a damage or improper function of the equipment if not performed correctly and may not be clear at first sight.

Example: This type of paragraph contains information that is used to illustrate how a specific function works.

2 Changes in the version 1.1.0

Note: **for detailed information see the Global Guide 1.1.0*

2.1 New features

- Support of remote display IV5.2*

2.2 Bug fixing

- N/A

3 Changes in the version 1.0.1

Note: *for detailed information see the Global Guide 1.0.0

3.1 New features

- > N/A

3.2 Bug fixing

- > Platform stabilization
 - » USB handling
 - » Email sending
 - » Date/time
 - » Handling of SNMP protocol

4 Notes

4.1 Document history

Revision number	Related sw. version	Date	Author
2	1.1.0	28.3.2025	Jakub Slavata
1	1.0.1	20.12.2023	Jakub Slavata